


June 2020 - Unauthorized Accessory Structure



Staircase



2016 Foreshore Inventory & Mapping Imagery – Area where sauna is now located



2017 Flood Imagery - Area where sauna is now located circled in red

